



**Photo 1 – View of helicopter showing airframe damage and resting on the left side.**



**Photo 2 – View top view of helicopter showing damage to rotor blades fuselage.**