



**Photo 1 – View of right aileron damage. (Courtesy of FAA)**



**Photo 2 – Front View of Airplane. (Courtesy of FAA)**





**Photo 3 – Zoomed in view of landing gear. (Courtesy of FAA. Note: Left Main Landing Gear Strut extended more than the Right Main Landing Gear Strut)**