



**Photo 1 – View of airplane at rest. (Courtesy of pilot)**





**Photo 2 – View of left wing damage (Courtesy of Insurance Adjuster)**



**Photo 3 – Wrinkle on lower section of fuselage. (Courtesy of insurance adjuster)**





**Photo 4 – View of fuselage. Circle notes a wrinkle that is difficult to see in photographs. (Courtesy of insurance adjuster)**