

ERA23LA379

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of Wreckage at Rest (Courtesy of FAA)



Photograph 2 - View of Right Side of Airplane (Courtesy of FAA)