



Photo 1 – View of left side of airplane showing structural damage



Photo 2 – View of aft of airplane showing structural damage



Photo 3 – View of right side of airplane showing structural damage



Photo 4 – View of right side of airplane showing post fire and structural damage.