



Photo 1 – Front View of Left Wing Damage – Courtesy of FAA



Photo 2 – Close Up of Left Wing Damage – Courtesy of FAA



Photo 3 – Side View of Left Wing Damage – Courtesy of FAA