

WPR23LA162

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Accident site, main wreckage. (Courtesy of the Airport Manager)**



**Photograph 2 - Accident site, fuselage damage. (Courtesy of the Airport Manager)**





**Photograph 3 - Accident site, view of the forward fuselage damage. (Courtesy of the Airport Manager)**



**Photograph 4 - Accident site, aft fuselage damage. (Courtesy of the Airport Manager)**