



**Photo 1 – Accident site, stabilizer, and tail rotor blade damage. (Courtesy of the helicopter operator)**



**Photo 2 – Accident site, tail rotor blade. (Courtesy of the helicopter operator)**



**Photo 3 – Accident site, tail boom. (Courtesy of the helicopter operator)**



**Photo 4 – Accident site, horizontal stabilizer damage. (Courtesy of the helicopter operator)**



**Photo 5 – Accident site, view from the fire extinguisher. (Courtesy of the helicopter operator)**