



**Photo 1 – Front right view of the airplane. (Photo courtesy of the FAA)**



**Photo 2 – View of the damage on the left side of the airplane. (Photo courtesy of the FAA)**



**Photo 3 – View of the left aileron bellcrank. (Photo courtesy of the FAA)**



**Photo 4 – View of the right aileron bellcrank. (Photo courtesy of the FAA)**