



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA20CA263



Photo 1 – View of Lower Airplane Fuselage (Photo Courtesy of Box Aviation)



Photo 2 – View of Propeller (Photo Courtesy of Box Aviation)




Photo 3 – View of Firewall Damage (Photo Courtesy of Box Aviation)