



Photo 1 – Main Wreckage (Photo Courtesy of Airport Supervisor)



Photo 2 – Main Wreckage Recovered (Photo Courtesy of Airport Supervisor)



Photo 3 – Nosegear (Photo Courtesy of Airport Supervisor)



Photo 4 – Steering Arm Assembly (Photo Courtesy of Piper Aircraft)



Photo 5 – Steering Horn Assembly (Photo Courtesy of Piper Aircraft)