



**Photo 1 – Airplane in Water (Photo Courtesy of N. Kaddatz)**



**Photo 2 – Airplane Being Recovered from Water (Photo courtesy of FAA)**





**Photo 3 – Leading Edge Damage of Right-Wing (Photo Courtesy of FAA)**





**Photo 4 - Leading Edge Damage to Left-Wing (Photo Courtesy of FAA)**



**Photo 5 – Damage to the Left-Wing Tip Area (Photo Courtesy of FAA)**