



**Photo 1 – Left Side View of Airplane at Accident Site**



**Photo 2 – Right Side View of Airplane at Accident Site**



**Photo 3 – Skid Marks and Airplane at Accident Site**



**Photo 4 – Right Main Landing Gear Pushed Up Through Right Wing**



**Photo 5 – Right Main Landing Gear**