



Photo 1 – View of the collapsed nose landing gear (Photo Courtesy of FAA)



Photo 2 - View of the fractured engine mount (Photo Courtesy of FAA)