



Photo 1 – View of the helicopter at the accident site (Photo Courtesy of FAA)



Photo 2 - View of the helicopter at the accident site (Photo Courtesy of FAA)



Photo 3 – View of the helicopter at the accident site (Photo Courtesy of FAA)



Photo 4 – View of power lines and the long line leading toward helicopter (Photo Courtesy of FAA)



Photo 5 – View of the helicopter cockpit (Photo Courtesy of Haverfield Aviation)



Photo 6 – View of the pulled belly band release handle postaccident (Photo Courtesy of Haverfield Aviation)