



Photo 1 – Screen Shot from Security Camera Video 1 Showing Nose Landing Gear Off Runway and Wrinkle on Left Side of Forward Fuselage – Courtesy of Pittsfield Municipal Airport



Photo 2 – Tracks in Grass Off Left Side of Runway - Courtesy of Pittsfield Municipal Airport



Photo 3 – Paint Chips from Nose Wheel Landing Gear Pant – Courtesy of Pittsfield Municipal Airport



Photo 4 – Nose Wheel Landing Gear Pant Showing Missing Paint - Courtesy of Pittsfield Municipal Airport



Photo 5 – Propeller Blade Showing Dirt from Ground Contact and Yellow Paint Transfer - Courtesy of Pittsfield Municipal Airport



Photo 6 – Left Side Forward Fuselage Wrinkle - Courtesy of Pittsfield Municipal Airport



Photo 7 – Close Up of Left Side Forward Fuselage Wrinkle - Courtesy of Pittsfield Municipal Airport



Photo 8 – Left Side Firewall and Fuselage Wrinkles - Courtesy of Pittsfield Municipal Airport



**Photo 9 – Right Side of Airplane Showing Fuselage Wrinkle and Missing Paint on Nose Wheel Landing Gear Paint -
Courtesy of Pittsfield Municipal Airport**



Photo 10 – Right Side Forward Fuselage Wrinkle - Courtesy of Pittsfield Municipal Airport



Photo 11 – Close Up of Right Side Forward Fuselage Wrinkle - Courtesy of Pittsfield Municipal Airport