



Photo 1 – Accident site, main wreckage.



Photo 2 – Accident site, runway impact marks.




Photo 3 – Accident site, runway impact marks.



Photo 4 – Accident site, runway impact marks.



Photo 5 – Accident site, lower fuselage damage.



Photo 6 – Accident site, leading edge of the right elevator damage.