



Photo 1 – View of Initial Ground Scar Facing Direction of Travel (FAA)



Photo 2 – View of Wreckage as Found Facing Direction of Travel (FAA)