



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA20LA237



Photo 1 – View of Airplane from Front (Photo Courtesy of Space Coast Regional Airport Manager)



Photo 2 – View of Airplane from Right (Photo Courtesy of Federal Aviation Administration)



Photo 3 – View of Airplane from Rear (Photo Courtesy of Federal Aviation Administration)



Photo 4 – View of Airplane from Left (Photo Courtesy of Federal Aviation Administration)



Photo 5 – View of Runway Skid Marks (Photo Courtesy of Space Coast Regional Airport Manager)



Photo 6 – View of Accident Airplane Skid Marks (Photo Courtesy of Space Coast Regional Airport Manager)



Photo 7 – View of Airplane and Ground Marks (Photo Courtesy of Federal Aviation Administration)



Photo 8 – Ground Scars from Landing Gear (Photo Courtesy of Space Coast Regional Airport Manager)



Photo 9 – Close-up View of Left Wing Damage (Photo Courtesy of Federal Aviation Administration)



Photo 10 – Close-Up View of Landing Gear (Photo Courtesy of Federal Aviation Administration)



Photo 11 – View of Left Main Landing Gear (Photo Courtesy of Federal Aviation Administration)