



Photo 1 – Horizontal Stabilizer Damage (FAA Photo)




Photo 2 - Horizontal Stabilizer Damage (FAA Photo)



Photo 3 – Lower Fuselage Damage (FAA Photo)



Photo 4 – Forward Fuselage Damage (FAA Photo)



Photo 5 – Forward Fuselage Damage (FAA Photo)



Photo 6 – Runway Tire Marks (FAA Photo)