



Photo 1 – Main Wreckage (Photo Courtesy of FAA)



Photo 2 – Empennage Damage (Photo Courtesy of FAA)




Photo 3 – Right Wing Damage (Photo Courtesy of FAA)