



Photo 1 – Airplane with Landing Gear Retracted on Runway (courtesy FAA)



Photo 2 – Deformation of Bulkhead (courtesy FAA)