



Photo 1 – Main Wreckage – Courtesy of Brokenstraw Soaring Club



Photo 2 – Area of Right Lower Wing Root – Courtesy of Brokenstraw Soaring Club



Photo 3 – Damage to Right Wing – Courtesy of Brokenstraw Soaring Club



Photo 4 – Damage to Right Wingtip – Courtesy of Brokenstraw Soaring Club



Photo 5 – Tire Mark from N912B – Courtesy of Brokenstraw Soaring Club



Photo 6 – Culvert – Courtesy of Brokenstraw Soaring Club