



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA376



Photo 1 – View of Left Wing Damage (Photo Courtesy of Pilot)



Photo 2 – View of Wing Damage from Left Wingtip (Photo Courtesy of Pilot)