



Photo 1 – Main Wreckage (Photo Courtesy of IA Genn)



Photo 2 – Right Main Landing Gear (Photo Courtesy of IA Genn)



Photo 3 – Skid Marks (Photo Courtesy of IA Genn)



Photo 4 – Propeller Strikes (Photo Courtesy of IA Genn)