



Photo 1 – View of the airplane damage sustained to the forward nose and engine area (Photo Courtesy of FAA)






Photo 2 – View of the damaged firewall (Photo Courtesy of FAA)





Photo 3 – Overview of the buckled empennage/ fuselage area (Photo Courtesy of FAA)