



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA020



Photo 1 – View of Airplane from Right Wing (Photo Courtesy of LYH Airport Operations)



Photo 2 – View of Airplane from Front (Photo Courtesy of LYH Airport Operations)



Photo 3 – Postaccident View of Johnson Bar (Photo Courtesy of LYH Airport Operations)



Photo 4 – Postaccident View of Cockpit Controls (Photo Courtesy of LYH Airport Operations)



Photo 5 – View of Runway Scar Leading to Airplane (Photo Courtesy of LYH Airport Operations)



Photo 6 – View of Belly Damage (Photo Courtesy of FAA)