



Photo 1 – Left Main Landing Gear (Photo Courtesy of FAA)



Photo 2 – Right Wing Damage (Photo Courtesy of FAA)



Photo 3 – Right Fuselage Damage (Photo Courtesy of FAA)