



**Photo 1 – Main Wreckage (Photo Courtesy of Recovery Company)**



**Photo 2 – Right Horizontal Stabilator (Photo Courtesy of Recovery Company)**





**Photo 3 – Fuel Selector (Photo Courtesy of Recovery Company)**