



**Photo 1 – View looking northwest with the approximate location of the accident site denoted by the red outline.**





**Photo 2 – View looking northwest with accident site denoted by the red outline.**





**Photo 3 - View looking northwest with accident site denoted by the red outline.**





**Photo 4 – View looking northwest, terrain scarring visible on north facing ridge impacted by the helicopter. Accident site denoted by red outline.**





**Photo 5 – North face of the ridge impacted by the helicopter and the surrounding terrain. Terrain scarring and debris field visible.**





**Photo 6 – Close up view of the north facing ridge impacted by the helicopter, terrain scarring and debris field visible.**





**Photo 7 - Accident helicopter at accident site. Photo provided by County of Kaua'i.**





**Photo 8 – Accident helicopter’s instrument panel mounted clock. Photo provided by Pacific Helicopter Tours, Inc.**