



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA093



Photo 1 – View of Airplane from Left Wing (Photo Courtesy of FAA)



Photo 2 – View of Airplane from Left Rear (Photo Courtesy of FAA)



Photo 3 – Close-up View of Left Wing Damage (Photo Courtesy of FAA)