



Photo 1 – Accident Site (Photograph courtesy of Cirrus Aircraft)



Photo 2 - Accident Site (Photograph courtesy of Cirrus Aircraft)



Photo 3 – Initial Impact (Photograph courtesy of Cirrus Aircraft)



Photo 4 – Main Wreckage (Photograph courtesy of Cirrus Aircraft)



Photo 5 – Main Wreckage (Photograph courtesy of Cirrus Aircraft)