

Photo 1 – Snow Disruption on Right Side of Runway with Airplane in the Background (FAA)



Photo 2 – Section of Landing Gear on Runway with Airplane in the Background (FAA)




Photo 3 – Forward Right-Side View of Airplane at Accident Site (FAA)




Photo 4 – Right Side View of Airplane in Hangar (FAA)



Photo 5 – Forward Left Side of Airplane in Hanger (FAA)




Photo 6 – Left Side View of Airplane in Hanger (FAA)



Photo 7 – Rear View of Airplane in Hangar (FAA)



Photo 8 – Right Side View of Airplane in Hanger (FAA)