



Photo 1 – Main Wreckage - Courtesy of FAA



Photo 2 – Rear View of Main Wreckage – Courtesy of FAA



Photo 3 – Ground Scar from Main Rotor – Courtesy of FAA



Photo 4 – Right Skid – Courtesy of FAA