



Photo 1 – Accident Site – Courtesy of City of Fernandina Beach



Photo 2 – Front View of Wreckage – Courtesy of City of Fernandina Beach



Photo 3 – Rear View of Wreckage – Courtesy of City of Fernandina Beach



Photo 4 -Right Side of Forward Fuselage – Courtesy of Florida Air Recovery



Photo 5 – Underside of Forward Fuselage – Courtesy of Florida Air Recovery



Photo 6 – Anti Skid Switch



Photo 7 – Emergency Brake Control Lever