



**Photo 1 – View of thermal damage to airplane firewall**





**Photo 2 – View of airplane left outboard wing**





**Photo 3 - View of airplane right outboard wing**





**Photo 4 – View of thermal damage to airplane horizontal stabilizer**