

CEN23FA333

**INVESTIGATION PHOTOGRAPHS**





**Photograph 1 - Accident helicopter**





**Photograph 2 - Accident gyroplane**





**Photograph 3 - Separated outboard sections of the helicopter main rotor blades**



**Photograph 4 - Gyroplane vertical and horizontal stabilizers**





**Photograph 5 - Gyroplane's separated rotor mast**