

WPR24LA216


INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of powered glider from front. (Courtesy of Iron County Sheriff's Dept.)



Photograph 2 - View of powered glider from left. (Courtesy of Iron County Sheriff's Dept.)



Photograph 3 - View of damage to empennage. (Courtesy of Iron County Sheriff's Dept.)

INVESTIGATION PHOTOGRAPHS