



**Photo 1 – View of the airplane in the house from the front of the house. (Photo courtesy of the FAA)**



**Photo 2 – View of the airplane in the house from the back of the house. (Photo courtesy of the Polk County Sheriff's)**



**Photo 3 – Aerial view of the airplane in the house. (Photo courtesy of the Polk County Sheriff’s)**



**Photo 4 – Front right view airplane.**




**Photo 5 – View of the right wing and engine.**



**Photo 6 – View of the left wing and engine, laying inverted.**




**Photo 7 – View of the cockpit controls, the flap and landing gear handles.**



**Photo 8 – Twin Seabee engine restart in flight checklist found in the wreckage.**





**Photo 9 – Twin Seabee Vmc demo checklist found in wreckage.**