



Photo 1 – View of the accident site. Courtesy of Colusa County Sheriff.



Photo 2 – View of the recovered wreckage.



Photo 3 - View of the recovered wreckage.



Photo 4 - Attitude indicator gyro and gimble.



Photo 5 - Recovered vacuum pump.



Photo 6 - Recovered vacuum pump.



Photo 7 - Recovered engine.