



Photo 1 – View the right side of the airplane. (Photo courtesy of FAA)



Photo 2 – View of the damage to the left side of the airplane. Photo courtesy of FAA)



Photo 3 – The airplane came to rest in the grass left of runway 08. (Photo courtesy of FAA)