



Photo 1 – View of the airplane at the accident site (Photo Courtesy of FAA)



Photo 2 - Buckling and substantial damage to the left wing (Photo Courtesy of FAA)



Photo 3 – View of the accident airplane and skid marks (Photo Courtesy of FAA)



Photo 4 – View of the nose gear postaccident (Photo Courtesy of FAA)



Photo 5 – View of the right main landing gear (Photo Courtesy of FAA)



Photo 6 – View of the left main landing gear (Photo Courtesy of FAA)