



Photo 1 – Rudder Damage (Courtesy of Instructor Pilot)



Photo 2 – Right Side Internal Structural Damage to Airframe. (Courtesy of Instructor Pilot)