



Photo 1 – View of the destroyed airplane (photo courtesy of Textron)



Photo 2 - View of empennage damage (photo courtesy of Textron)



Photo 3 - View of right main landing gear (photo courtesy of Textron)



Photo 4 - View of accident airplane engine (photo courtesy of Textron)



Photo 5 - View of accident airplane propeller (photo courtesy of Textron)