



Photo 1 –N7721C Piper PA-32R-300 at the accident scene after recovery from deeper water. (Source: Yute Commuter Services)



Photo 2 - View of substantial damage to the forward fuselage and engine. (Source: Yute Commuter Services)



Photo 3 - Front view of wreckage. (Source: Yute Commuter Services)



Photo 4. - Wreckage left side. (Source: Yute Commuter Services)



Photo 5 - Wreckage right side with right wing and propeller damage evident. (Source: Yute Commuter Services)