



**Photo 1 – View of front of airplane showing fuselage buckling**



**Photo 2 – View of aft of airplane showing vertical stabilizer buckling**