



Photo 1 – View of left wing showing buckling damage on outboard section of wing (FAA Photo)



Photo 2 – View of left side of the fuselage showing buckling aft of door. (FAA Photo)