



**Photo 1 – Aft view of accident airplane.**



**Photo 2 – Accident airplane’s substantially damaged rudder.**



**Photo 3 – Accident airplane's fractured rudder post.**