




**Photo 1 – Overall view of helicopter after removal from accident site**





**Photo 2 – Damage to fuselage structure**