



Photo 1 – Left rear view of aft fuselage at accident site



Photo 2 – Left rear view of airplane at accident site



Photo 3 – Main landing gear separated from airplane



Photo 4 – Aft fuselage at accident site



Photo 5 – Aircraft at accident site



Photo 6 – Aft view of strakes



Photo 7 – Right ventral strake



Photo 8 – Left ventral strake